Approved For Release 2006/10/17 : CIA-RDP81B00878R000600050085-2

25X1

[redacted]

24 Feb. 59,

STATINTL

1. The major change in Service Bulletin ~~Out~~ procedures are as follows.

a. [redacted] heretofore had the responsibility for certifying actions concerning service bulletins. As you can see this presents problems in that Bob would be certifying "after-the-fact" and did not have the prerogative of interceding should ~~there be~~ questions because all actions were usually complete including delivery of kits, futhermore requirements for the issuance of a service bulletin is more in the technical field than the support field.

b. In view of this the directive for the test site included approval & review of service bulletin requirements to include approval from inception to completion.

2. This writer had the impression this had been coordinated with entrested parties at LAC, regardless, minor changes ~~to~~ in the service bulletin format use

Approved For Release 2006/10/17 : CIA-RDP81B00878R000600050085-2

Approved For Release 2006/10/17 : CIA-RDP81B00878R000600050085-2

require changes to indicate approval by the Commander of the test site from inception to completion. This of course is a minor change and should be worked on "jointly" by LAC & test site Commander to resolve any difficulties.

Approved For Release 2006/10/17 : CIA-RDP81B00878R000600050085-2